

Design, Analysis and Research Corporation (DARcorporation)

ERRATA: Airplane Design Part III

Copyright ©1986-89 by Dr. Jan Roskam

Year of Print, 1986, 1989

(Errata Revised October 11, 2001)

- page 15, Table 2.3* Switch values for β_1 and β_2
- page 22, Figure 2.14* The + or – 5 degree lines should be drawn from the engine centerlines, not the aircraft centerlines.
- page 194, 8th line from top* replace “stability” with “Stability”.

Please check the website www.darcorp.com for updated errata