

ERRATA: Airplane Design Part III

Copyright ©1986-89 by Dr. Jan Roskam

Year of Print, 1986, 1989

(Errata Revised April 14, 2011)

- page 15, Table 2.3* Switch values for β_1 and β_2
- page 22, Figure 2.14* The + or – 5 degree lines should be drawn from the engine centerlines, not the aircraft centerlines.
- page 194, 8th line from top* replace “stability” with “Stability”.
- page 267, Figure 5.11* + and – must be interchanged on the C_m axis.