

ERRATA: Airplane Design Part VI

Copyright © 2004 by Dr. Jan Roskam

Year of Print, 2004

(Errata Revised October 19, 2007)

- page 28, 4th line* add “in radians” after wing twist angle.
- page 205, Eqn. 6.48* Delete second row of numbers in the table. Third row corresponds to $(\eta_{inl/inc} SHP_{av} - P_{extr})$
- page 229, Eqn. 8.7* δ_f in the second term should be replaced by $\delta_{f1} + \delta_{f2}$.
- page 259, 9th line* add “at $\alpha = 0$ ” after leading edge flaps.
- page 273, Figure 8.65c* All capital subscripts “H” should be lower case subscript “h”
- page 357, Table 9.1* Third row, second column 0.8 should be replaced by -0.8.
- page 401, variable description for Eqn. 10.47* Add ‘deg⁻¹’ after σ_{β_α} , σ_{β_Γ} , $\sigma_{\beta_{\varepsilon_t}}$
Add ‘deg’ after α_f , Γ , ε_t
- page 430, Figure 10.42* Y-axis values should be divided by -4
- page 461, Eqn. 10.123* should be multiplied by η_v