

ERRATA: Airplane Design Part III

Copyright ©2002 by Dr. Jan Roskam

Year of Print, 2002

(Errata Revised November 17, 2014)

Please check the website www.darcorp.com for updated errata

- page 70, Table 3.4* The third column header for the Number of Required Exits should be 'TYPE III'.
- page 267, Figure 5.11* $C_m > 0$ should be $C_m < 0$.
- page 267, Figure 5.11* + and – must be interchanged on the C_m axis.