

ERRATA: Airplane Design Part VI

Copyright © 2008 by Dr. Jan Roskam

Year of Print, 2008

(Errata Revised September 22, 2015)

Please check the website www.darcorp.com for updated errata

page 239, Eqn. 8.19 δ_f should be multiplied by η_δ , from the equation's description

page 273, Figure 8.65c All capital subscripts "H" should be lower case subscript "h"