

ERRATA: Airplane Design Part VII

Copyright © 2002 by Dr. Jan Roskam

Year of Print: 2006

(Errata Revised February 1, 2017)

Please check the website www.darcorp.com for updated errata

page 11,

last sentence of 3rd para.

Typical numerical values for gearing ratios are given in Table 4.1 of Part IV, not Part VI.